




Structurally Deficient Bridges on the National Highway System 1st Congressional District of Washington, 2003

Structure Number	Road	Location
1	0001956A0000000	SR 522 2.1 E JCT SR 104
2	0006980B0000000	STATE ROUTE 522 6.6 E JCT SR 9
3	0013685A0000000	SR104 8.9 E JCT SR 3
4	084391000000000	228TH ST S.W. .5 E INT I-405



U.S. Department of Transportation
Bureau of Transportation Statistics
Federal Highway Administration

The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,643 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.